


TechMemo #04-0004



PRIORITY:	Normal
DATE:	April 5, 2004
TITLE:	AlphaEclipse 3600 Sign Wireway Pinouts Label Correction
ECO REFERENCE:	n/a
PRODUCT(S) AFFECTED:	AlphaEclipse 3600 Signs
SUMMARY:	This document contains the correct AlphaEclipse 3600 sign wireway pinouts label.

Wireway pinouts label

The wireway pinouts label in the AlphaEclipse 3600 sign may be incorrect. For TB4 (Main 232), 1 is actually RS232 TxD and 2 is RS232 RxD.



Pages 21, 22, 24, 25, 26, 27 of the AlphaEclipse Sign Installation Instructions (pn 9711-8001) manual show the incorrect label and will be updated at the next manual release.

© Copyright 2004 Adaptive Micro Systems LLC. All rights reserved.

Adaptive Micro Systems • 7840 North 86th Street • Milwaukee, WI 53224 USA • 414-357-2020 • 414-357-2029 (fax) • http://www.adaptivedisplays.com Trademarked names appear throughout this document. Rather than list the names and entities that own the trademarks or insert a trademark symbol with each mention of the trademarked name, the publisher states that it is using names for editorial purposes and to the benefit of the trademark owner with no intention of improperly using the trademark. The following are trademarks of Adaptive Micro Systems: Adaptive, Alpha, AlphaLert, AlphaNET, AlphaNet plus, AlphaEclipse, AlphaPremiere, AlphaTicker, AlphaVision, AlphaVision InfoTracker, Automode, BetaBrite, BetaBrite Director, BetaBrite Messaging Software, Big Dot, Director, EZ KEY II, EZ95, PagerNET, PPD, PrintPak, Serial Clock, Smart Alec, Solar, TimeNet. The distinctive trade dress of this product is a trademark claimed by Adaptive Micro Systems LLC.

Due to continuing product innovation, specifications in this manual are subject to change without notice.

April 5, 2004 04-0004 (This page intentionally left blank.)